

Do not tighten the screws too tight and make sure to use the non-loctite adhesive to adhere the screws.
(The CNC tail pitch link should be able to operate freely after the screws were tightened and adhered)

M1. 4X4螺絲勿鎖過緊，並使用螺絲止鬆劑黏著。
並請注意銅襯組裝方向。

